

IN THE UNITED STATES PATENT & TRADEMARK OFFICE

IN RE APPLICATION OF: U.S. Patent No. 7,738,618

USPTO CONFIRMATION CODE: 9268

APPLICATION NO.: 10/595,426

PCT FILED: October 23, 2003

U.S. FILED: January 16, 2008

EXAMINER: Shuwang Liu

GROUP ART UNIT: 2611

FOR: MULTIBAND PLL ARRANGEMENT AND A METHOD OF CONTROLLING  
SUCH ARRANGEMENT

37 CFR 1.322 & 37 CFR 1.323 REQUEST FOR CERTIFICATE OF CORRECTION  
FOR USPTO AND/OR APPLICANT MISTAKE

HONORABLE COMMISSIONER OF PATENTS & TRADEMARKS

SIR:

The following is a request for a certificate of correction in Serial Number 10/595,426, now Patent Number 7,738,618.

A certificate of correction under 35 USC 254 is respectfully requested in the above-identified patent.

The errors were the fault of both the applicant and USPTO and, accordingly, please charge \$100.00 to our Deposit Account No. 50-1379. In the event that a further fee is required, please charge the amount to the same Deposit Account.

The exact locations where the errors appear in the patent and patent application are as follows:

In Column 1, Line 64, delete “cone” and insert - - done - -, therefor.  
(ORIGINALLY FILED SPECIFICATION DATED JANUARY 7, 2009, PAGE 2, LINE 28)

In Column 4, Line 61, delete “amplitude,” and insert - - amplitude - -, therefor.  
(ORIGINALLY FILED SPECIFICATION DATED JANUARY 7, 2009, PAGE 9, LINE 3)

In Column 10, Line 59, after “while the” delete “The”.  
(ORIGINALLY FILED SPECIFICATION DATED JANUARY 7, 2009, PAGE 21, LINE 26)

In Column 16, Line 4, delete “etc.)” and insert - - etc. - -, therefor.  
(ORIGINALLY FILED SPECIFICATION DATED JANUARY 7, 2009, PAGE 32, LINE 14)

In Column 16, Line 5, delete “(The” and insert - - The - -, therefor.  
(ORIGINALLY FILED SPECIFICATION DATED JANUARY 7, 2009, PAGE 32, LINE 16)

The requested corrections are attached on Form PTO 1050.

Respectfully Submitted

, 2010

---

DATE

/SIDNEY L. WEATHERFORD,Reg#45602/

---

Sidney L. Weatherford  
Registration No. 45602  
Attorney of Record